



State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Supervisor ARZ

Inspection Report Minerals Regulatory Program

Report Date: May 26, 2005

Mine Name: Bluffdale Sand and Gravel Operator or Permittee Name: Bluffdale Sand and Gravel Permittee Mailing Address: 5635 Waterbury Way, Ste. C-100, Salt Lake City, 84121	Inspec UT	t number: S/0 tion Date: Ma er: Clear, 70's	ay 17 and 24,	2005	
Inspector(s): Paul Baker	Inspec 2:15 PM	Inspection Start Time: 10:40 AM & 2:15 PM Inspection End Time: 11:15 AM &			
Other Participants: Tom Gyuro (Bluffdale Sand and Gravel) Permit Status: Active Current Acreages:: Total Permitted (Bonded): 5 Total Disturbed: 5	2:30 PM Site location/Area Inspected (i.e. Pit #): Entire permitted area Surface Ownership: Fee Mineral Ownership: Fee Mineral Mined: Landscape rock Type of Mine: Surface				
Elements of Inspection 1. Permits, Revisions, Transfer, Bonds	Evaluated	N/A	Comment	Enforcement	
2. Public Safety (open shafts, adits, trash,					
signs, highwalls) 3. Protection of Drainages					
4. Explosives, magazines					
5. Deleterious Material6. Roads (maintenance, surfacing, dust control,			Ц		
safety)					
7. Concurrent Reclamation8. Erosion Control9. Demolition					
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)					
11. Water Impoundments 12. Soils 13. Revegetation 14. Air Quality 15. Facilities 16. Other					



Inspection Date: May 17 and 24, 2005; Report Date: May 26, 2005

Page 2 of 2 S/035/022

Purpose of Inspection:

The operator has requested partial release of the bond.

Inspection Summary:

8. Erosion Control

Although there is no vegetation, there is enough rock on the surface that I expect few or no erosion problems. It had rained just before I arrived at the site on May 17, and I saw no sign whatever of erosion.

10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes) The site blends well with surrounding areas. There were no highwalls, shafts, or similar public safety hazards.

13. Revegetation

The operator seeded a mixture of barley and crested wheatgrass for interim vegetation cover. This is not an ideal time of year to seed, so there may be minimal growth resulting from this seeding. Nevertheless, if there is adequate moisture for weeds to grow, there should be enough water for the barley and crested wheatgrass to compete with the weeds. I anticipate it will be necessary to reseed in the fall.

Conclusions/Recommendations:

The operator has requested partial release of the bond from \$17,000 (the release request letter actually says \$17,500, but the bond is \$17,000) to \$5000. I believe the grading has been adequate and that the Division only needs to hold enough money for revegetation.

2 BM

Inspector's Signature

Date:

May 26, 2005

PBB:jb

Enclosures: Photo Attachment cc: Tom Gyuro, Operator

Blaine Gehring, Bluffdale City

O:\M035-SaltLake\S0350022-Bluffdale\inspections\ins-05242005.doc

ATTACHMENT

Photographs

S/035/022, Bluffdale Sand and Gravel Mine, Bluffdale Sand and Gravel Inspection Dated: May 17 and 24, 2005; Report Dated: May 26, 2005



Photo 1. A portion of the regraded area. Note the amount of rock on the surface.



Photo 2. Another view of the regraded area. There was no erosion in spite of recent rain.



Photo 3. This photo and Photo 4 show a new area where the operator intends to mine landscaping rock.



Photo 4.